

# Application Success

## SURFACE FINISHING PLANT Corrosive Environment



Failed Gauge



Corrosion-Free OBS Series Plastic Pressure Gauges

When an Ohio plating company needed reliable pressure measurement of the pumps that protect their process plating machines, they turned to **Icon Process Controls**.

The environment within this area of the plating process was very corrosive. The metal pressure gauges that were being installed were only lasting for a couple of months, before they became corroded and in turn prematurely failed and had to be replaced.

The ongoing replacement of these gauges was not only costly but also very time consuming. For this reason, Icon suggested the use of our **Truflo OBS Series Industrial Pressure Gauges**, designed to outperform in extremely corrosive services.

The **OBS series plastic pressure gauge** are available in many different pressure ranges, and every plastic pressure gauge come complete with three colored pressure range markers that provides quick visual pressure indication.

**Truflo OBS Series Plastic Pressure Gauges and Gauge Guard** have been designed for industry's toughest applications.

Icon Process Controls ...Corrosion-Free Instrumentation Specialists



For more information contact us at [sales@iconprocon.com](mailto:sales@iconprocon.com) or 905.469.9283

